

Crary Shoes
 Orthopedic Modifications
 Price List

Modifications					
L3410	Rocker bottom	for simple soles- using same sole		\$90.00	per unit/each foot
L3410	Rocker bottom	for complicated soles and using new Vibram soles		\$100.00	per unit/each foot
L3410	Rocker bottom	spring steel		\$150.00	per unit/each foot
L3310	Lift	up to	1/4"	\$100.00	
	Lift	up to	1/2"	\$120.00	
	Lift	up to	3/4"	\$130.00	
	Lift	up to	1"	\$140.00	
	Lift	up to	1 1/2"	\$165.00	
	Lift	up to	2"	\$200.00	
L3310	Interior Lift	Consultation fee must be paid in addition to this if appt is needed		\$ 40.00	up to 3/8"
				\$ 50.00	up to 1/2"
				\$ 60.00	up to 3/4"
For each additional 1/4" above 2", add \$25.00					
The higher the lift, heel flares can become necessary. Add \$25.00					
The prices listed above are for soles that peel off or can be cut off in one piece.					
For other styles of soles, prices increase an additional \$20-30+					
Please avoid Dr. Martins and shoes that have air pockets or gel in the soles. We will turn them away.					
If you are unsure, bring it by our Airport Way location and we will be happy to take a look.					